

~~TOP SECRET~~  
OXCART/TRINE

BYE 2753-67  
Copy 5 of 11

27 December 1967

Job # 69B 00404R  
Box #1 Folder 31

MEMORANDUM FOR THE RECORD

SUBJECT: Critique for OXCART Mission Number BX6740

1. Mission critique was conducted in the OSA Control Center at 1400 hours, 21 December 1967.

2. Mission Data:

- a. Mission Number: BX6740
- b. Date Flown: 16 December 1967
- c. Area of Operation: North Vietnam
- d. Mission Success: Successful
- e. Pilot's Name: Layton
- f. Aircraft Number: 131
- g. Primary or Spare Flown: Primary
- h. Takeoff Time - Planned: 0120Z  
Actual: 0120Z
- i. Landing Time - Planned: 0522Z  
Actual: 0516Z
- j. Time Enroute - Planned: 4+02  
Actual: 3+56
- k. Departure Base: Kadena AB
- l. Landing Base: Kadena AB
- m. Equipment:

(1) Primary: Type I, BW, PIN PEG, MAD MOTH, BLUE DOG II, SYSTEM VI.

(2) Spare: Same as primary.

3. Operations:

- a. Route (INS Plot vs Planned): Satisfactory.

HANDLE VIA BYEMAN  
COMINT CONTROL  
CHANNELS JOINTLY

OXCART/TRINE  
~~TOP SECRET~~

~~TOP SECRET~~  
OXCART/TRINE

BYE 2753-67  
Page 2

(1) INS Terminal Error: 4.5NM

(2) INS Spec Error: 10.3NM

b. Mission Generation & Operation Support:  
Satisfactory.

4. Weather:

a. Forecast vs. Actual:

(1) As briefed.

(2) Comments: Weather slightly better than  
briefed 17 - 19° north.

5. Intelligence:

a. Target Coverage:

(1) 9 of 12 programmed targets covered.

(2) 0 first priority SSM targets of 9 covered.

(3) 6 of 27 first priority NVN COMOR targets  
covered.

(4) 110 SAM sites, 2 sites occupied, 1 new  
site.

(5) 8 other priority NVN COMOR targets covered.

(6) Comments: Broad, excellent coverage with  
a low percentage of clouds was obtained on the  
high interest areas of NV. This included high  
priorities SSMs search areas. Significant new  
information was collected on a wide variety of  
targets such as SAM sites airfields, posts, bridges  
and communications centers.

HANDLE VIA BYEMAN  
COMINT CONTROL  
CHANNELS JOINTLY

OXCART/TRINE  
~~TOP SECRET~~


~~TOP SECRET~~  
OXCART/TRINE

BYE 2753-67  
Page 3

b. Quality of Take: Satisfactory.

(1) Resolution: Good

(2) Camera Operation: Normal



e. EWS Activations: None

f. Take Movement:

(1) Photography: Satisfactory

(2) ELINT: Satisfactory

6. Materiel:

a. Aircraft General: Satisfactory.

(1) Fuel gage erratic after first A/R for remainder of mission.

(2) Drage chute was slow deploying.

b. Aircraft Systems: Satisfactory

(1) System VI recorder capstan belt broke prior to second pass over denied.

(2) Spurious signals recorded on System VI tape (first pass).

HANDLE VIA BYEMAN  
COMINT CONTROL  
CHANNELS JOINTLY

OXCART/TRINE  
~~TOP SECRET~~

~~TOP SECRET~~  
OXCART/TRINE

BYE 2753-67  
Page 4

7. Communications: Satisfactory
- a. Message Traffic: Satisfactory
  - b. Birdwatcher: Satisfactory
  - c. UHF/HF Commo: Satisfactory


8. Significant Actions Taken:

Reference paragraph 6a:

- (1) Fuel gage error caused by corrosion and has been repaired.
- (2) Drag chute was damp due to moisture and deploy action was normal under existing conditions.

9. Outstanding Actions Required:

- a. Investigate above normal ground speed recorded during first penetration leg. (OXC/PLANS)
- b. Determine thru COMINT if North Vietnamese Air Defense System was engaged in activities against theater aircraft during BX overflight. (INTEL/OSA)
- c. Investigate spurious signals recorded on System VI tape. (Office of ELINT; D/M/AVD).
- d. Research reason for and probability of additional failure to system VI capstan belt. (D/M/AVD)

  
WILLIAM E. SHELTON  
Colonel, USAF  
Deputy for Operations, OSA

HANDLE VIA BYEMAN  
COMINT CONTROL  
CHANNELS JOINTLY

OXCART/TRINE  
~~TOP SECRET~~

~~TOP SECRET~~  
OXCART/TRINE

BYE 2753-67  
Page 5

OXC/OSA/[ ] (27 Dec 67)  
Distribution:

- #1 - D/SA
- #2 - D/O/OSA
- #3 - D/M/OSA
- #4 - D/R&D/OSA
- #5 - OXC/OSA
- #6 - INTEL/OSA
- #7 - WEA/OSA
- #8 - COMMO/OSA
- #9 - ADP/OSA
- #10 - RB/OSA
- #11 - Chrono

HANDLE VIA BYEMAN  
COMINT CONTROL  
CHANNELS JOINTLY

OXCART/TRINE  
~~TOP SECRET~~